Work Orde													Page 1
Revision ID:	D3916-5 Light Rib			,	Accept					Setup	Start Stop	1 10011101 0	
	21/04/2010	Start Qt Req'd Q	-			Cust Item II Customer:	D:				Stop		
Approvals:	Process Pla	n:	B-1	Date: 16-11-21	Tooling: SPC (Y/N):		te: te:		×	Run	Start Stop		
Sequence ID/ Work Center II		Operatio Descripti			Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr				•							
Large Fab			*** Make li	50" e with manuel pipe bender a ne at 9.00" annd use jig for o ess tube material to finish siz	s per D19366 other line***	AD 10-05-0	7	•	9)	10.0)5.	07	
QC Quality Control			ct part compl Memo	eteness to step on W/O	0.00	عارة اره			49				
120 Packaging Packaging		ldentify as p	oer dwg & Sto	ock Location: WA	0.00 SA 0.00 10	D -05-10		. (9				

Dart Aerospace	Ltd
----------------	-----

W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
······										
Part No	:	PAR #:	Fault Categ	ory:	NCR:	Yes N	lo DQ /	\ :	_ Date: _	
	Re	esolution:	Disposition	:	QA: I	VC Clo	sed:		Date: _	
NCR:	-		WORK ORDE	R NON-CONFORM	ANCE	(NCR))			
DATE	STEP	Description of NC			ction B	O: 0	Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
					i					
		,								
				,						
	:									
				·						
778										
ı				•						
-		!								

Work Order ID 57982

April 21, 2010 10:06:24 AM



Page 2

Item ID:

D3916-5

Accept



Setup Start

Stop



Revision ID:

Item Name: Light Rib

Start Date:

21/04/2010 Start Qty: 6.00

Required Date: 21/04/2010 Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference: Approvals:

Process Plan:

Date:

Tooling:

Draw

Run Start



QC:

Date:

SPC (Y/N):

Date: Date:

Plan

Stop

Sequence ID/ **Work Center ID**

130

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**

Number

Draw Rev.

Accept Code Qty

Reject Qty

Reject Number Stamp

Insp.

Memo

0.00

0.00

Quality Control

W/O:			WO	RK ORDER CHAN	IGES	 <u>-</u>				
DATE	STEP	, P	ROCEDURE CHAN	IGE	В	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		1								
Part No	:	PAR #:	Fault Categ	ory:	NCR: \	es N	o DQA	\ <u>. </u>	Date:	
		esolution:								
NCR:			WORK ORDE	R NON-CONFOR	MANCE (N	ICR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action S Action Description	Section B	gn &	Verific		Approval	Approval
		SectionA	Chief Eng	Chief Eng		ate	Section	on C	Chief Eng	QC Inspector
		1								
									- V-2-11-2-1	,
					į					
······································						<u> </u>		· · · · · ·		
		1								
		T.								

Picklist Print

April 21, 2010 10:06:29 AM

Work Order ID: 57982

Parent Item:

D3916-5

Parent Item Name: Light Rib

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC

as per dwg revA 10.03.15 verified by:EC



IPP Rev:B

Start Date: 21/04/2010

Required Date: 21/04/2010

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name

M304TS0.500W.049

Replacement Mfg/ Item ID Purch

Purchased

Primary Bin Item Location No

Last Location Route Seq ID 100

Unit of Measure Hand

Qty on

Remaining Qty To Pick 317.5306 26.3116

Date Issued

Status

Page 1

Qty


Issued

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
MAT	298		
114426	298		39.4674
Main Warehouse			,
MAT018	19.5306		
114004	3.5		***
114161	16.0306		ت ر

Square Tubing

Dart Ae	rosi	pace	Ltd
---------	------	------	-----

	•								
W/O:		1	WO	RK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval QC Inspector	
		1							
		1					<u> </u>)	
		I							
Part No	•	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A:	_ Date: _	***
	Re	esolution:	Disposition	1:	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector
		1							
		1							
		'							
		1							
		:							
		ı							



	•									
W/O:		1	WO	RK ORDER CHANG	GES					
DATE	STEP	PR	OCEDURE CHAP	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,									
		1								
Part No	•	PAR #:	Fault Categ	ory:	NCR	: Yes N	lo DQ	A:	Date:	
		esolution:								
NCR:		:	WORK ORDE	R NON-CONFORM	ANCE	(NCR)	1		-	
DATE	STEP	Description of NC			ction B		Verific	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
		i								
		'								
		1								
		1							2-101	
		1								
		,								
		1								
		i								
		*					1].

-D3916-1 RIB D3759-1-BUSHING 7 PL

W1057982

D3916-041 RIB ASSY


NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: NONE
7) WEIGHT -041: 1.84 lbs
8) WELD PER DART QSI 004

D


DESIGN	AJS	DART AEROSPACE L	īD
DRAWN	JPH	HAWKESBURY, ONTARIO, CANA	
CHECKED	a	DRAWING NO.	REV. A
MFG. APPR.	12	D3916	SHEET 2 OF 4
APPROVED	L AND	TITLE	SCALE
DE APPR.	-	RIB ASSY, 350 BASKET	NTS
DATE 10.0	3.04	COPYRIGHT © 2010 BY DART AEROSPACE THIS COCLARENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRES NOT TO BE USED FOR ANY AUGUSTS; OR COPED OR COMMUNICATED TO ANY OTH-	S CONDITION THAT IT IS

D

W/O:				WC	RK ORDER CHAN	GES					
DATE	STEP		PRO	OCEDURE CHAI	NGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	<u>.</u>										
		i .									
	:	1							,		
<u> </u>											
Part No	:		PAR #:	Fault Cate	gory:	NCR: Y	es No	DQ/	A :	_ Date: _	
	R	esolution:		Disposition	ı:	QA: N/0	Clos	ed:		Date: _	
NCR:			,	WORK ORDE	R NON-CONFORM	IANCE (N	CR)				
DATE	STEP	De	escription of NC	Initial		ection B	ın &		ation		Approval
			Section A	Chief Eng	Action Description Chief Eng	D	ate	Section	on C	Chief Eng	QC Inspector
				·							
								·			
	\$.										
		1									
		:									
		l l	,	·							



W/O:				W	ORK ORDER CHANG	iES				
DATE	STEP		PR	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		ı								
		1								
Part No	•	:	PAR #:	Fault Cat	legory:	_ NCR: Yes	No DQ	A :	Date:	
					on:					
NCR:	•	i		WORK ORI	DER NON-CONFORM	ANCE (NC	R)		· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	1	Description of NC			ion B	Verifi	cation	Approval	Approval
DAIL	SILF		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
		,								
										<u> </u>
									•	
		,								
		1								
		1								
							i			



Dart Aerospace L	≥ Ltd	pace	eros	A)art	
------------------	-------	------	------	---	------	--

W/O:		WORK ORDER CHANGES										
DATE	STEP		PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		•										
		*.	•						÷			
		•										
			•									
Part No	:	•	PAR #:	Fault Category:	NCI	R: Yes	No DQ	A :	_ Date: _			
	Re	esolution:		Disposition: QA			A: N/C Closed:			_ Date:		

			WORK ORDER NON-CONFORMANCE (NCR)										
STEP	Description of NC	Corrective Action Section B			*Verification	A							
	Section A	Initial Chief Eng			Section C	Approval Chief Eng	Approval QC Inspector						
	·			•									
,	,												
			. *										